

Phase Diagram







Phase Data


Pige W

Caliber S1000	30	28	27	26	24	22	20	61:	18	91	14	12	6	9	4	2	0	-2	4	9-	-8	-10	-12														
Caliber C1500	29	29	28	26	24	22	20	18	15	13	10	7	4	-	-2	5-	ထု	-11	-14	-21	-25	-29	-33	-37	-43	67-	95-	-63	0.2-	-63	-55	47	-40				
Caliber M1000	29	27	56	52	23	22	20	18	16	14	11	8	9	2	-2	9-	-11	-17	-23	-29	-35	-42	49	-56	£9 -	-71	-79	-82	-85	:							
Ice Ban M80	58	28	27	25	23	21	19	11	15	13	11	6	7	4	-	2-	5-	8-	-11	-15	-19	-23	-27	-31	-34	-37	-40	-41	-42	-43	44	-45					
ice Ban M50	30	30	29	29	28	27	26	25	24	23	22	21	20	19	17	15	13	12	10	6	7	9	5	4	2	1	0	-3	9-	6-	-12	-15	-17	-21	-28	-35	-40
NaCi	28	27	56	24	23	22	20	19	17	16	14	12	11	6	7	5	2	0	-3	-5	1	13	28														
CaC12	30	29	28	26	24	22	20	18	16	14	12	10	8	5	2	-1	4	8-	-12	-16	-20	-25	-31	-38	46	-53	-52	-34	-17								
MgC12	29	26	25	24	22	20	18	16	13	10	7	4	0	-3	- 8	-13	-17	-23	-27	-20	-14	-10	9-	-3	-1	1	2									·	
% DS	4	2	9	7	œ	6	40	+	12	13	44	15	16	17	18	19	20	21	22	23	24	25	26	27	28	53	30	31	32	33	34	35	36	37	38	39	40




9 % Increase in Ice Penetration 45 -- 20 F -- 10 F -- 0 F Minutes 30 5 200% 160% 120% 80% 40% %0





PNS Method



Friction Values

